



Notice of Designation of Maintenance and Obsolete Thick-Film Hybrid ICs (Affected products: Products listed below)

Thank you for using SANYO semiconductor products. We will be introducing the technology mentioned in the title as described below. Please take note of this introduction.

Memorandum

Affected Products:

STK405-030	STK407-070	STK408-090E
STK405-030A	STK407-070E	STK4102MK2
STK405-050	STK407-090	STK4112MK2
STK405-050A	STK407-090E	STK4122MK2
STK405-070	STK407-100	STK4132MK2
STK405-070A	STK407-100E	STK4142MK2
STK405-090	STK407-110	STK4152MK2
STK405-090A	STK407-110E	STK4162MK2
STK405-100	STK407-120	STK4171X
STK405-100A	STK407-120E	STK4172MK2
STK405-110	STK407-240	STK4182MK2
STK405-110A	STK407-250	STK4192MK2
STK405-120	STK407-270	STK4201MK2
STK407-040	STK407-290	STK4211MK2
STK407-040E	STK408-040E	STK4221MK2
STK407-050	STK408-050E	STK4231MK2
STK407-050E	STK408-070E	STK4241MK2

Reason for Designation:

To optimize the product lineup.

Date of Implementation:

September 2001.

Contact your SANYO sales representative if you have any questions or require more detailed information regarding this change.